

ABSTRACT

Methods and systems for monitoring the delivery of workpieces to a position by: storing a digital reference image of the position prior to the delivery of workpieces; storing a digital operating image of the position during delivery of workpieces; performing image arithmetic on the reference image and the operating image to produce a digital evaluation image comprised of a plurality of pixels; establishing a threshold image condition for the evaluation image that correlates to the existence of an operating condition relevant to the control of the delivery of workpieces; and examining the pixels in the evaluation image to determine whether the threshold image condition is met.

DRAFT - 4/20/94